

DRIVER/VEHICLE EXAMINATION REPORT

Colorado State Patrol  
Motor Carrier Safety  
15075 South Golden Road  
Golden, CO 80401  
Phone: (303)273-1875

Report Number: CO2B51210050  
Inspection Date: 08/18/2022  
Start: 12:55 PM MT End: 1:30 PM MT  
Inspection Level: II - Walk-Around  
HM Inspection Type: None

Carrier: F3 SYSTEMS INC

DBA:

3775 BRICKWAY BLVD STE 100  
SANTA ROSA, CA, 95402

USDOT: 1384069

Phone#: (707)584-9900

MC/MX#: 527439

Fax#:

State#:

Location: MONUMENT POE NB  
Highway: I25

Driver: [REDACTED]

License#: [REDACTED]

State: [REDACTED]

Date of Birth: [REDACTED]

CoDriver:

License#:

State:

Date of Birth:

Milepost: 161 Shipper: N/A

Origin: COLORADO SPRINGS,  
CO

Bill of Lading: N/A

Destination: DENVER, CO

Cargo: EMPTY

County: EL PASO

Email:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA #	Issued #	OOS Sticker
1	TR	FRHT	2020	IN	349195	249	3AKJHLDR1LSLV8588	26000			

BRAKE ADJUSTMENTS: No brake measurements required for level II or level III

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Special Checks:	Placard:	Cargo Tank:
Alcohol/Controlled Substance Check	Traffic Enforcement	Post Crash Inspection
X Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
Size and Weight Enforcement	Drug Interdiction Search	
eScreen Inspection		
MCSAP Overtime	High Priority Overtime	

Report Prepared By: D.CONWAY  
ID/Badge #: 1536

Copy Received By: [REDACTED]

X

X



01384069 CO CO2B51210050

DRIVER/VEHICLE EXAMINATION REPORT

Colorado State Patrol  
Motor Carrier Safety  
15075 South Golden Road  
Golden, CO 80401  
Phone: (303)273-1875

Report Number: CO2B51210051  
Inspection Date: 08/18/2022  
Start: 1:10 PM MT End: 1:45 PM MT  
Inspection Level: II - Walk-Around  
HM Inspection Type: None

Carrier: JONES BROTHERS TRUCKING INC

DBA:

PO BOX 4414  
MISSOULA, MT, 59806

USDOT: 205056

MC/MX#: 159075

State#:

Location: MONUMENT POE NB

Highway: I25

County: EL PASO

Email:

Phone#: (406)721-4629

Fax#:

Driver: [REDACTED]

License#: [REDACTED]

Date of Birth: [REDACTED]

CoDriver: [REDACTED]

License#: [REDACTED]

Date of Birth: [REDACTED]

State: [REDACTED]

State:

Milepost: 161 Shipper: N/A

Origin: COLORADO SPRINGS,  
CO

Destination: DENVER, CO

Bill of Lading: N/A

Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA #	Issued #	OOS Sticker
1	TR	FRHT	2020	IN	PA19609	519	3AKJHHRXLSLJ924	26000			

BRAKE ADJUSTMENTS: No brake measurements required for level II or level III

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Special Checks:

- X Alcohol/Controlled Substance Check
- X Conducted by Local Jurisdiction
- Size and Weight Enforcement
- eScreen Inspection
- MCSAP Overtime

Placard:

- Traffic Enforcement
- PASA Conducted Inspection
- Drug Interdiction Search
- High Priority Overtime

Cargo Tank:

- Post Crash Inspection
- PBBT Inspection

Report Prepared By: D.CONWAY  
ID/Badge #: 1536

Conv Received By: [REDACTED]

X

X



DRIVER/VEHICLE EXAMINATION REPORT

Colorado State Patrol  
Motor Carrier Safety  
15075 South Golden Road  
Golden, CO 80401  
Phone: (303)273-1875

Report Number: CO2B51210052  
Inspection Date: 08/18/2022  
Start: 1:20 PM MT End: 1:50 PM MT  
Inspection Level: II - Walk-Around  
HM Inspection Type: None

Carrier: COINSTAR LLC

DBA:

330 120TH AVE NE  
BELLEVUE, WA, 98005

USDOT: 787081

MC/MX#:

State#:

Location: MONUMENT POE NB

Highway: I25

County: EL PASO

Email:

Phone#: (425)943-8000

Fax#:

Driver: [REDACTED]

License#: [REDACTED]

Date of Birth: [REDACTED]

CoDriver:

License#: [REDACTED]

Date of Birth: [REDACTED]

State: [REDACTED]

State:

Milepost: 161 Shipper: N/A

Origin: COLORADO SPRINGS,  
CO

Destination: AURORA, CO

Bill of Lading: N/A

Cargo: COINS

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA #	Issued #	OOS Sticker
1	TR	FRHT	2019	IN	3401053	701	3ALACKFC5XDK57690	33000			

**BRAKE ADJUSTMENTS:**No brake measurements required for level II or level III

**VIOLATIONS:**No violations were discovered

**HazMat:** No HM transported

Special Checks:	Placard:	Cargo Tank:
Alcohol/Controlled Substance Check	Traffic Enforcement	Post Crash Inspection
X Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
Size and Weight Enforcement	Drug Interdiction Search	
eScreen Inspection		
MCSAP Overtime	High Priority Overtime	

Report Prepared By: D.CONWAY  
ID/Badge #: 1536

Copy Received By: [REDACTED]

X

X



DRIVER/VEHICLE EXAMINATION REPORT

Colorado State Patrol  
Motor Carrier Safety  
15075 South Golden Road  
Golden, CO 80401  
Phone: (303)273-1875

Report Number: CO2B51210053  
Inspection Date: 08/18/2022  
Start: 1:30 PM MT End: 2:00 PM MT  
Inspection Level: II - Walk-Around  
HM Inspection Type: None

Carrier: MAHONEY TRANSPORTATION SERVICES  
LLC

DBA:  
712 ESSINGTON ROAD  
JOLIET, IL, 60435

USDOT: 304078  
MC/MX#: 004394  
State#:

Phone#: (800)982-9392  
Fax#:

Location: MONUMENT POE NB  
Highway: I25

County: EL PASO  
Email:

Driver: [REDACTED]

License#: [REDACTED]

Date of Birth: [REDACTED]

CoDriver:

License#:

Date of Birth:

State: [REDACTED]

State:

Milepost: 161 Shipper: N/A  
Origin: COLORADO SPRINGS,  
CO  
Destination: DENVER, CO

Bill of Lading: N/A

Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA #	Issued #	OOS Sticker
1	TR	FRHT	2022	IL	P1134035	143	3ALACXFC3NDND5778	33000			

BRAKE ADJUSTMENTS: No brake measurements required for level II or level III

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Special Checks:

- Alcohol/Controlled Substance Check
- Conducted by Local Jurisdiction
- Size and Weight Enforcement
- eScreen Inspection
- MCSAP Overtime

Placard:

- Traffic Enforcement
- PASA Conducted Inspection
- Drug Interdiction Search
- High Priority Overtime

Cargo Tank:

- Post Crash Inspection
- PBBT Inspection

Report Prepared By: D.CONWAY  
ID/Badge #: 1536

Copy Received By: [REDACTED]

X

X



00304078 CO CO2B51210053

DRIVER/VEHICLE EXAMINATION REPORT

Colorado State Patrol  
Motor Carrier Safety  
15075 South Golden Road  
Golden, CO 80401  
Phone: (303)273-1875

Report Number: CO2B51210054  
Inspection Date: 08/18/2022  
Start: 1:40 PM MT End: 2:10 PM MT  
Inspection Level: II - Walk-Around  
HM Inspection Type: None

Carrier: CONCRETE PUMP PARTNERS LLC  
DBA:  
3950 DICKERSON PIKE  
NASHVILLE, TN, 37207  
USDOT: 1528195 Phone#: (615)299-9899  
MC/MX#: Fax#:  
State#:

Driver: [REDACTED]  
License#: [REDACTED] State: [REDACTED]  
Date of Birth: [REDACTED]  
CoDriver:  
License#: State:  
Date of Birth:

Location: MONUMENT POE NB  
Highway: I25

Milepost: 161 Shipper: N/A  
Origin: COLORADO SPRINGS,  
CO  
Destination: DENVER, CO

Bill of Lading: N/A  
Cargo: CONCRETE PUMPER

County: EL PASO  
Email:

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA #	Issued #	OOS Sticker
1	TR	MACK	2022	IN	4334654	135	1MZTE2GC6NM007539	54000			

BRAKE ADJUSTMENTS: No brake measurements required for level II or level III

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Special Checks:	Placard:	Cargo Tank:
Alcohol/Controlled Substance Check	Traffic Enforcement	Post Crash Inspection
X Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
Size and Weight Enforcement	Drug Interdiction Search	
eScreen Inspection		
MCSAP Overtime	High Priority Overtime	

Report Prepared By: D.CONWAY  
ID/Badge #: 1536

Copy Received By: [REDACTED]

X

X

